: FWD BLADE FOLD ASSY WELDMENT

€ User:

Wednesday, 29/10/2008 10:13:49 AM

Melanie Fauteux

**Process Sheet** 

Customer

: CU-DAR001 Dart Helicopters Services

**Job Number** 

: 43063 **Estimate Number** : 13418

P.O. Number

This Issue : 29/10/2008

Prsht Rev. : NC

: // First Issue **Previous Run** 

: 42753

S.O. No. :

: LARGE FAB ASSY Type

Part Number

: PB674300107

**Drawing Number** 

**Drawing Name** 

· B6743001 P.5

**Project Number** 

: N/A : B1

**Drawing Revision** 

Material

**Due Date** 

: 05/11/2008

Qty:

Each

1 Um:

Written By

Checked & Approved By

Comment

: Est Rev:A

08-06-25 new issue DD verified by:ec

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

**Description:** 

1.0

PB674300147

Base Assembly

PB6743001205

Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Base Assembly batch: 343055

Comment: Qty.:

1.0000 Each(s)/Unit

Total:

1.0000 Each(s)

Outer Tube



(08-11-27

3.0



Comment: Qty.:

1.0000 Each(s)/Unit

Total:

1.0000 Each(s)

4.0

PB674300121



Comment: Qty.:

6.0000 Each(s)/Unit Total:

6.0000 Each(s)

Square Tubing

5.0

PB6743001209

batch:-

Square Tubing



Comment: Qty.:

1.0000 Each(s)/Unit Total:

Square Tubing

1.0000 Each(s)

Dark Aerospace Ltd W¿Ò: 🔑 **WORK ORDER CHANGES** Approval **Approval** DATE STEP PROCEDURE CHANGE By Qty Chief Eng / Prod Mgr Date QC Inspector Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_ WORK ORDER NON-CONFORMANCE (NCR) NCR:

DATE	STEP	Description of NC	1	Corrective Action Section B	Verification	Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
				11/				
1						·		
				•				
				<b>3</b>				
				<b>1</b> ,				
								A.M.

NOTE: Date & initial all entries

Date: Wednesday, 29/10/2008 10:13:49 AM User: Melanie Fauteux **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: FWD BLADE FOLD ASSY WELDMENT // Job Number: 43063 Part Number: PB674300107 /Job Number: Seq. #: **Machine Or Operation: Description:** PB6743001201 Square Tubing Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Square Tubing batch: 41572 08-11-04 PB6743001203 7.0 Square Tube Comment: Qtv.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Square Tube batch:- 41789 ME 08-11-04 PB6743001207 8.0 Square Tube Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) / los:11.27 Square Tube batch: <u>B</u> 43199 V PB6743001219 9.0 Angled Male Eye Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Angled Male Eye batch:-\_\_\_B 4004 08-11-04 10.0 D34405 Contoured Detent Clip Base (Supersedes B Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Contoured Detent Clip Base batch:batch:-<u>08-11-04</u> MF 11.0 D34407 Detent Clip Base (Supersedes B67-43001-2 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **Detent Clip Base** 71 20**74** batch:-08-11-04 D344015 12.0 Contoured Male Eye (Supersedes B67-43001 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Contoured Male Eye 08-11-04 1302 batch:-MF

Dart Aerospace Ltd

WĄO:		WORK ORDER CHANGES											
DATE STEP		PROCEDURE CHANGE			В	y	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		• ·						:					
		PAR #:	Fault Cate	gory:	NCR: \	es N	lo <b>DQ</b> A	\:	Date:				
		olution:	n: Disposition:			C Clos	sed:		Date:				
NCR:			WORK ORDE	ER NON-CONFORM	MANCE (N	ICR)							
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action S Action Description Chief Eng		ign & Date	Verific Section		Approval Chief Eng	Approval QC Inspector			
									-				
wa a													
					ļ								
	1   1		1				1		1	1			

NOTE: Date & initial all entries

Date: Wednesday, 29/10/2008 10:13:49 AM User: Melanie Fauteux **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: FWD BLADE FOLD ASSY WELDMENT Job Number: 43063 Part Number: PB674300107 Job Number: Seq. #: **Machine Or Operation: Description:** 13.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1- assemble parts on jig DT8813 and weld as per dwg PB67-43001 \*\*\* ensure no burn thru after welding in tube -205 and -197 only where bushing -265 \*\*\* 14.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION QC5 15.0 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 16.0 POWDER COATING POWDER COATING 102316 Comment: POWDER COATING \*\*\*mask inside of D3440-5, D3440-7 and D3440-15 prior to paint\*\*\*\* Powder Coat Green Sandtex (Ref: 4.3.5.8) as per QSI 005 4.3 START TIME: **OVEN TEMPERATURE** FINISH TIME: 17.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERS Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING ' 18.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock 19.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion

-			
	<b>Aeros</b>	- 1	
I IOT	AAPAC	naca	1 1/1
	ACI US	vave	L IU

W(O:		WORK ORDER CHANGES										
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
					يان.							
		PAR #:										
		Resolution:	Disposition:			QA: N/C Closed: Date:						
NCR:			WORK ORDE	R NON-CONFORMA	NCE	(NCR	)			-		
		Description of NC Section A	Corrective Action Section B		on B		Verification		Approval	Approval		
DATE	STE		Initial Chief Eng	Action Description Chief Eng		Sign & Date		Section C	Chief Eng	QC Inspector		
										5		
							ļ					
							İ					
		·								ļ		

NOTE: Date & initial all entries

